
Various Routes
D 1 OVD SIN STR REPL 2010-29
Various Counties
Sheet 9 of 16



•• If walkway bracket at safety chain location is behind sign, add angle to bracket, see Alternate Safety Chain Attachment on Base Sheet OS-A-11.

For Details T and W, Section B-B and Grating Splice Details see Base Sheet OS-A-10. For Handrail Details see Base Sheet OS-A-11.

	<del></del>
•	- 2
) <u>.</u>	
-	
)S-A-9	 5/16/08

Structure Number	Station	<b>a</b> .	b	с	d	е	Walkway Grating and Handrail Lengths
ISO45U030R000.0-001	98 + 90	N/A	N/A	N/A	N/A	N/A	70′ - 0"
1S045S056L000.0	100 + 50	N/A	N/A	N/A	N/A	N/A	67' - 0"
IS0161057R341.9.0	229 + 20 NB	N/A	N/A	N/A	N/A	N/A	111':- 6"
150161057L342.4	257 + 00 SB	N/A	N/A	N/A	N/A	N/A	112' - 6"
1S0161080R153.0	1503 + 00 EB	N/A	N/A	N/A	N/A	N/A	69′ - 6"
1S0161080R154.3	1577 + 25 EB	N/A	N/A	N/A	N/A	N/A	89′ - 6"
150161094L000.0	43 + 80	N/A	N/A	N/A	N/A	N/A	60′ - 0"
1S0161057L345.0	395 + 60 SB	N/A	N/A	N/A	N/A	N/A	116" - 6"
150161057L344.6	374 + 00 SB	N/A	N/A	N/A	N/A	N/A	128' - 6"
IS0161057R344.6	372 + 35 NB	N/A	N/A	N/A	N/A	N/A	109' - 6"
IS0161057R345.0	390 + 20 NB	N/A	N/A	N/A	N/A	N/A	106' - 6"
IS0161080R153.0	1503 + 00 EB	N/A	N/A	N/A	N/A	N/A	69' - 0"

OVERHEAD SIGN STRUCTURES
ALUMINUM WALKWAY DETAILS

District 1 Sign Structure Repair and Replacement